



NuPower II

WATERLESS, DRYWASH CLEANER & POLISH with UV PROTECTANT

For normal or lightly oxidized soiled surface conditions



GENERAL CLEANING

1. Apply **NuPower II** as is – DO NOT DILUTE by hand, with mophead or random orbital.
2. Agitate a small, 18-24" area evenly with the product.
3. Allow to dry 5-10 minutes. It will "haze" over.
4. Remove by buffing-out with clean mophead, or dry terry towel, or a clean bonnet head on random orbital.

**Product dilutions are determined by extent, condition & soil type.*

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.

QUESTIONS? NUVITE technicians have the answers 800.394.8351